

ADR	HEXADR	NAME	Description	shadow	OS
31	\$001F	PTEMP		none	A

Temporary register used by the printer handler for the value of the character being output to the printer.